

Smart Diagnostics® 3.4

Welcome to 3.4

8/1/2017

With the addition of an Alerts Heat Map and Sentry Dashboards this version provides improved ways to visualize machine health.

New Features

Alerts Heat Map




Features:

- View multiple types of alarm data
- Additional data levels
- Analog and Discrete Color Scales
- Click and Drag Zooming
- Multiple Time Interval selections
- Single click level navigation
- One click Trend Navigation at Indicator level

Example: How to View a Week With 8h Shifts

1. Click 'Custom' on the time range selector in the top right
2. Set the 'Start Date' to be the beginning of the week with the time set to start of first shift
3. Set the 'End Date' to be the end of the week with the time set to the end of the last shift
4. Submit the time range
5. Select 8h from the dropdown menu next to the 'Custom' button
6. The image will refresh and each cell will now correspond to an 8h shift.



Dashboards

Disclaimer: Currently Dashboards and their associated features can only be created by KCF Sentry Engineers. Please contact your Sentry Representative to get started.

Dashboard Features

- Create Custom Dashboards Corporation and Location Levels
- Visualize Alarm Data From
 - Corporation Dashboard: Groups and Locations
 - Location Dashboard: Groups and Indicators
- Customizable Page Layout
- Full Screen Mode
- Additional Color Schemes
- Multiple Widgets
 - Gauge
 - Value
 - Time Series Graph
 - Pie Chart